

City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Belle Isle



The exterior of the boat club had peeling paint, crumbling walls, a broken window and unsafe stairs.

City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Belle Isle

Scott Fountain

Overall Evaluation – Good Condition

- Overall structure appeared to be sound.
- Grounds and shrubs around the fountain were neatly kept.
- There were some water stains on the monument.



The fountain was in working condition with neatly trimmed shrubs and free of litter. Some water stains on fountain were shown.

City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Belle Isle



The fountain appeared to have a sound structure and was well maintained.